

# **TML-3 SERIES**









**Tactile Switch** 

#### **SPECIFICATION**

**△MECHANICAL** 

Operation Force: 160±50gf Brown (N)

Stroke: 0.25+0.2/-0.1mm

Operation Temperature:  $-20^{\circ}$ C to  $+70^{\circ}$ C Storage Temperature:  $-30^{\circ}$ C to  $+80^{\circ}$ C

**△ELECTRICAL** 

Electrical Life: 50,000 cycles for 160gf

Rating:50mA, 12VDC

Contact Resistance: 100mΩ max.

Insulation Resistance:  $100M\Omega$  min. 500V DC Dielectric Strength: 250VAC / 1 minute Contact Arrangement 1 pole 1 throw

LED: See Specification.

#### **MATERIAL**

**△Cover**: UL 94V-0 Nylon High-temp Thermoplastic.

Color: White

**△STEM**: UL 94V-0 Nylon High-temp Thermoplastic.

Color: Black

**△CONTACT**: Stainless with silver cladding.

**△BASE**: UL 94V-0 Nylon High-temp Thermoplastic.

Color: White(160gf)

△TERMINAL: Brass, Silver cladding

△ADHESIONS TAPE : Kapton

### SOLDERING PROCESS

△HAND SOLDERING: Use a soldering iron of 30 watts, controlled at 350°C approximately Max 5 seconds while

applying.


△REFLOW SOLDERING: When applying reflow soldering, the peak temperature or the reflow oven should be set

to 260℃ max.

△CONDITION FOR SOLDERING : Reflow & non-washable

type


#### 



TIME(sec)

## **PACKING**

Part Number	Number Per Reel	Number Per Bag			
TML-3	3000	-			



Carrier Length:			76M/22" Paper reel(			( 13" F	13" Plastic reelx3)		Q'ty:3000pcs/13"reel			
ITEM	W	Αb	В₀	Kο	Р	F	E	Do	D <sub>1</sub>	Po	P <sub>2</sub>	t
DIM	16.0 <sup>+0.30</sup>	4.3 +0.10 -0.10	8.6 <sup>+0.10</sup> -0.10	2.7 +0.10 -0.10	B.O +0.10 -0.10	7.5 +0.10 -0.10	1.75 <sup>+0.10</sup> -0.10	1.50 <sup>+0.10</sup> -0.00	1.50 <sub>MIN.</sub>	4.00 <sup>+0.10</sup> -0.10	2.00 <sup>+0.10</sup> -0.10	0.35+0.0

General Tolerance: ±0.1mm

## PRECAUTION in HANDLING

△After reflow, do not touch LED before cooling, or it could influence LED function.

△It is a normal material characteristic when yellowing on plastic surface after reflow.

riangleCare should be exercised so that flux from the upper part of the printed circuit board does not adhere to the switch